

USB9603 Rev A1

User Product Information

National Semiconductor
September 2000
Revision 1.2



This document provides information on revision A1 of the National Semiconductor USB9603 chip.

This chip is available in two 28-pin packages: SOIC and CSP. The markings on line 2 of the respective package indicate the chip name; the markings on line 3 identify the chip revision.

Note that new information, added since the previous revision of this User Product Information, is marked with change bars.

Workarounds

Use the USB9604 device instead of the USB9603 for bus-powered applications.

The only difference between these two devices is the effect of a hardware reset on the clock generation circuit. In the USB9604, asserting the RESET input causes the clock generation circuit to be reset; in the USB9603, the clock generation circuit is not reset. For further details, refer to the USB9603/USB9604 datasheet.

1. CHIP

Revision A1 silicon has been analyzed and the following issues were found.

1.1 Voltage Regulator Output

The Voltage Regulator output value (pin V3.3) is slightly higher than the nominal voltage for default startup conditions. This same voltage is also fed to the USB transceivers.

Workaround

To obtain an accurate 3.3V value, write 0x40 to the Voltage Regulator Control Register, VREGCTL, at address 0x1f. (This is an internal test register, not documented in the datasheet.) All other values in this register should remain as is.

1.2 Stopping the Clock on XIN

If the clock on XIN is stopped when the USB9603 is not in HALT mode, the device locks up in an undefined state.

Workaround

Make sure that the device is in HALT mode before stopping the clock on XIN. For additional information, see the application note entitled "USB9603/4 Clock Stopping User Notes".

1.3 VBUS Brown-out after Warm Boot in Host PC

When a warm boot is performed in the host PC, the chipsets' USB hubs can create a brown-out on VBUS (VBUS voltage drops below the minimal voltage, approximately 1V, for a short period of time, approximately 20 msec).

This behavior is not defined in the USB specification, and falls under the inter-operability problem category.

Under these conditions, in a bus-powered application, USB9603 power-down sensing is not activated. In addition, the internal clock doubler that is reset by a power-up reset does not recover reliably, and the device can stop operating.



“电子爱好者”网站是一个面向广大电子爱好者、大专院校学生、中小型企业工程技术人员的电子技术应用、推广专业网站。主要内容有：电子技术应用交流，器件资料、电子设计软件下载，电子技术支持服务，电子产品发布、转让和引进等信息。

本资料由“电子爱好者”网站收集整理，版权属原作者

在使用本资料或软件时，有什么问题，欢迎到“电子爱好者”网站内的 BBS “技术论坛”中发表，我站的热心网友会帮助你的。

技术论坛：<http://www.etuni.com/bbs>

需要更多的电子技术相关资料或软件，欢迎到“电子爱好者”网站下载。

“电子爱好者”网站：<http://www.etuni.com>

LIFE SUPPORT POLICY

NATIONAL'S PRODUCTS ARE NOT AUTHORIZED FOR USE AS CRITICAL COMPONENTS IN LIFE SUPPORT DEVICES OR SYSTEMS WITHOUT THE EXPRESS WRITTEN APPROVAL OF THE PRESIDENT AND GENERAL COUNSEL OF NATIONAL SEMICONDUCTOR CORPORATION. As used herein:

1. Life support devices or systems are devices or systems which, (a) are intended for surgical implant into the body, or (b) support or sustain life, and whose failure to perform, when properly used in accordance with instructions for use provided in the labeling, can be reasonably expected to result in a significant injury to the user.
2. A critical component is any component of a life support device or system whose failure to perform can be reasonably expected to cause the failure of the life support device or system, or to affect its safety or effectiveness.



National Semiconductor Corporation, Americas
Tel: 1-800-272-9959
Fax: 1-800-737-7018
Email: support@nsc.com

National Semiconductor Europe
Fax: (+49) 0-180-530 85 86
Email: europe.support@nsc.com
Deutsch Tel: (+49) 0 69 9508 6208
English Tel: (+44) 0 870 24 0 2171
Français (+33) 0 1 41 91 87 90

National Semiconductor Asia Pacific
Tel: 65-254-4466
Fax: 65-250-4466
Email: ap.support@nsc.com

National Semiconductor Japan Ltd.
Tel: 81-3-5639-7560
Fax: 81-3-5639-7507
Email: nsj.crc@jksmt.nsc.com